



1. Adjust Cp for $V_{ab} = 1.05 V_{ac}$
2. Adjust Cs for $V_{bc} = V_{ab}$
3. Adjust Cpf for minimum line current

| Pony-Start Rotary Phase Converter | | |
|--------------------------------------|------------|-----------|
| Part Number | n/a | Rev D |
| Engineer | Jim Wilson | |
| Date | 11/11/2009 | Sheet 1/1 |